

December 2, 1987

Administrator

National Highway Traffic Safety Administration 400 Seventh Street, S.W.

Washington, D.C. 20590

0122-K/118-

JRIOMA IRO

27/7

Dear Ms. Gardner:

In accordance with the reporting requirements of Chapter V of Title 49 Code of Federal Regulations Part 565 (Prior FMVSS 115) Vehicle Identification Number, we submit the following addendum information necessary to decipher the characters contained in our Vehicle Indentification Number effective with the 1988 Model Year. This supplements our letter of August 11th.

Our World Manufacturer Identifier (WMI) Code as given to us by the Society of Automotive Engineers (SAE) is 1C9 (Crown Coach Incorporated), with the 3rd, 4th, and the 5th characters of the Vehicle Indentifier Section to be 102 (BUS).

## VIN - DECIPHER INFORMATION

4 - Model or Line

	MODEL	CODE		
Add:	2A-36-5Ø5	T		
	2A-38-5ØØ	U		
	2A-38-5Ø5	v		

7 - Engine Type

	MFGR	FUEL	NO. CYL	DISP	BHP	ENGINE	CODE
Add:	Cummins Cummins	Diesel Diesel	6	5Ø5 5Ø5	24Ø 21Ø	6CTA8.3 6CT8.3	G H

If there are any questions regarding the above information please contact the undersigned at (714) 591-0567.

Sincerely,

James A. Cowan, Jr.

Director of Engineering

cc: J.R. Pursell

E.G. McMahon

P. Huber

13799 Monte Vista Avenue • Chino, CA 91710-5513 • (714) 591-0567 • TELEFAX (714) 591-0567 Ext. 333