



Registration authority for ISO 3780

The Society of Automotive Engineers has been appointed by ISO to act as registration authority for the implementation of International Standard ISO 3780.

December 9, 2022

Jacob Harper Southland Golf Cart 2945 Logan Martin Dam Rd Vincent AL 35178-9443

Dear Jacob Harper,

As the agent of the National Highway Traffic Safety Administration for the assignment of manufacturer identifiers pursuant to CFR 49 Part 565 Vehicle Identification Number Requirements (VIN), the following World Manufacturer Identifier (WMI) Code has been reserved:

WMI Code	4S9	Positions 1, 2 & 3 of VIN
WMI Extension	658	Positions 12th, 13th & 14th of VIN
Manufacturer	Southland Golf Cart 2945 Logan Martin Dam Rd Vincent AL 35178-9443	
Country	United States	
Vehicle Type	Low speed vehicles	
Make/Model	Southland LSV	

If changes occur, such as company name, ownership, address and/or phone number, please be sure to notify us as soon as possible.

If you have questions concerning the construction of your Vehicle Identification Number, please contact the National Highway Traffic Safety Administration (NHTSA) Crash Data and Manufacturer Hotline at:

Email: manufacturerinfo@dot.gov Phone: 1-888-399-3277 Fax: 1-202-366-1024

> 400 Commonwealth Drive Warrendale, PA 15096 www.sae.org

o +1.724.772.8511 f +1.724.776.0243 e ksiddall@sae.org Thank you.

Sincerely,

Theirs Siddall

Kris Siddall CSR / WMI Coordinator

400 Commonwealth Drive Warrendale, PA 15096 www.sae.org o +1.724.772.8511 f +1.724.776.0243 e ksiddall@sae.org