



U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE.
Washington, DC 20590

OCT 25 2013

Mr. David Arff
Pittsburgh Glass Works LLC
30 Isabella St., Suite 500
Pittsburgh, PA 15212

Dear Mr. Arff:

This is in reply to your recent request. Our records have been updated to include the address change for the Elkin, NC plant. The plants that remain under the assigned DOT number code "904" are as follows:

Main Office

Pittsburgh Glass Works LLC
30 Isabella St., Suite 500
Pittsburgh, PA 15212

Plant Offices

Creighton Glass Plant - Works 1
P.O. Box 295
150 Ferry Street
Creighton, PA 15030-0295

Evert Glass Plant - Works 23
6251 S. Lauman Road
Evert, MI 49631

Crestline Glass Plant - Works 26
P.O. Box 269
5066 Lincoln Highway
Crestline, OH 44827

Tipton Glass Plant - Works 27
P.O. Box 307
Route 220
Tipton, PA 16684-0307

Evansville Glass Plant - Works 28
424 E. Inglefield Road
Evansville, IN 47725

Berea Glass Plant - Works 41
2290 Menelaus Road
Berea, KY 40403

Pittsburgh Glass Works, Poland Sp. Z o. o.
ul. Szhlana 1
Komorniki Dolnoslaskie Poland 55-300

Elkin
300 PGW Drive
Elkin, NC 28621

The use of the DOT symbol molded into or onto glazing material constitutes a certification by the manufacturer and signifies that the glazing material meets applicable Federal safety requirements. While it is not required that glazing materials be tested prior to using the DOT symbol, the National Highway Traffic Safety Administration does maintain a compliance test program to enforce safety standards, and any glazing materials that are found not to meet the Federal standards are subject to civil penalties of up to \$6,000 per item but not to exceed \$16,375,000 for any related series of violations.

The glazing material manufacturer's identification code mark is required on all glazing material sold in the United States for highway use. This code mark and other glazing material identification labeling are specified in the glazing material standard.

Should you no longer need an ID code mark or if any one of the following events occur, please notify us immediately, including the date of the change and the month, day and year the last glazing materials were produced using the codes in question, so that our records can be updated:

1. There is a change in company or plant name or address.
2. The company or plant is closed.
3. The company or plant is sold or merged with another company.
4. There is a change in the types of glazing materials manufactured at each plant.

On any future correspondence concerning a glazing material plant or the parent glazing material company, please reference the glazing material plant ID code(s) involved.

Sincerely,



Jeffrey Giuseppe
Chief, Equipment Division
Office of Vehicle Safety Compliance