



B210/24/88
-
pdg

01-22-N11B-3164

October 18, 1988

ORIGINAL

Ms. Patti Gardner
VIN Coordinator
National Highway Traffic
Safety Administration
400 Seventh Street, S.W., Rm. 5307
Washington, D.C. 20590

1 pg.

Dear Ms. Gardner:

In accordance with the reporting requirements of Chapter V of Title 49, Code of Federal Regulations, Part 565 (Prior FMVSS 115) Vehicle Identification Number, we submit the following addendum information necessary to decipher the characters contained in our vehicle identification number effective with the 1989 model year. This supplements our letters of June 29th and September 7, 1988.

Our World Manufacturer Identifier (WMI) Code, as given to us by the Society of Automotive Engineers (SAE), is 1C9 (Crown Coach Incorporated), with the 3rd, 4th and 5th characters of the Vehicle Identifier Section to be 102 (BUS).


VIN - DECIPHER INFORMATION:

4 - Model or Line

	<u>MODEL</u>	<u>CODE</u>
add:	2R-36N-552	2

If there are any questions regarding the above information, please contact the undersigned at (714) 591-0567.

Sincerely,


James A. Cowan, Jr.
Director of Engineering

JAC/jbt

cc. B. Freeman
E. McMahon
S. Marx